

6839416




FIG. 1




FIG. 2

66 70	72	74	76	78	
				CONFERENCE	DISABLE
80	1			ANNOUNCE	NO ANNOUNCE
	A	12	5	<input type="checkbox"/>	<input type="checkbox"/>
	joe@cisco	9	4	<input type="checkbox"/>	<input type="checkbox"/>
	56.0.0.112	VPI/VCI	0	<input type="checkbox"/>	<input type="checkbox"/>
82	214-953-6500	3	8	<input type="checkbox"/>	<input type="checkbox"/>
	john@cisco	2	3	<input type="checkbox"/>	<input type="checkbox"/>
	x5102	72.1.1.39	6	<input type="checkbox"/>	<input type="checkbox"/>
	x5108	7	5	<input type="checkbox"/>	<input type="checkbox"/>
	C	1	1	<input type="checkbox"/>	<input type="checkbox"/>
	128	193	0	<input type="checkbox"/>	<input type="checkbox"/>
	408-555-1000	11	9	<input type="checkbox"/>	<input type="checkbox"/>
:	:	:	:	:	:

FIG. 3

66 70	72	74	76	78	
				CONFERENCE	DISABLE
80	1			ANNOUNCE	NO ANNOUNCE
	A	12	5	<input type="checkbox"/>	<input type="checkbox"/>
	joe@cisco	9	4	<input type="checkbox"/>	<input type="checkbox"/>
	56.0.0.112	VPI/VCI	0	<input type="checkbox"/>	<input type="checkbox"/>
82	214-953-6500	3	8	<input checked="" type="checkbox"/>	<input type="checkbox"/>
	john@cisco	2	3	<input type="checkbox"/>	<input type="checkbox"/>
	x5102	72.1.1.39	6	<input type="checkbox"/>	<input type="checkbox"/>
	x5108	7	5	<input type="checkbox"/>	<input checked="" type="checkbox"/>
	C	1	1	<input type="checkbox"/>	<input type="checkbox"/>
	128	193	0	<input type="checkbox"/>	<input type="checkbox"/>
	408-555-1000	11	9	<input checked="" type="checkbox"/>	<input type="checkbox"/>
:	:	:	:	:	:

FIG. 4

00643315-082100




FIG. 5

06643315-082100

FIG. 6

